Errata

NFPA 72
National Fire Alarm Code®

2002 Edition

Reference: (Various)
Errata No.: 72-02-2 (draft)

The Committee on Signaling Systems for the Protection of Life and Property notes the following editorial corrections for the 2002 edition of NFPA 72, *National Fire Alarm Code®*.

1. *In Subsection 2.3.1 revise the title of ANSI/UL 827 to read Standard for Safety Central-Station Alarm Services*, 1996

2. *In Figure 5.14.6.5.1.1 add the words* "or wall" *to/column three in the heading and subheading for Parts B, D, and F so that the heading reads* Ceiling or wall mounted *and the subheading reads* Smoke detector ceiling or wall mounted.

3. *In Subsection 6.8.6.4.1 add the word* "Emergency" *to the Title of ANSI S3.41 so that it reads "American National Standard Audible Emergency Evacuation Signal".*

4. *In Paragraph B.3.3.6.6.1 revise the second sentence to read* "The pallets are stored 0.5 m (1.5 ft) high".

5. *In Subsection B.5.3.3 revise the legend for equation B.66 to remove the redundant set of words"* radiant power emitted by test spark" *after the symbol P.*

Issue Date: April 16, 2003

Copyright© 2003 all Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION